


Aim: give physical insight into the DQ transformation and its implementation

1. SIMPLIFIED EXPLANATION


a 3-ph surface PM machine can be represented by the following equivalent circuit



voltages and currents in each phase are balanced: equal magnitudes 120° out of phase


- $e_a$ : induced voltage due to PM
- $L$ : inductance of phase
- $v_a$ : terminal phase voltage
- $i_a$ : phase current

can define d-axis and q-axis currents by their phase relationship with the induced voltage  $e$ , consider phase A




- q-axis current  $i_q$  is in-phase with  $e$
- d-axis current  $i_d$  is out of phase with  $e$

consider the instantaneous power  $e_a i_q$  and  $e_a i_d$



only the q-axis current produces average power in a surface PM machine



simplified phasor diagram for a surface PM machine

note that changing the d-axis current does not affect the torque but does affect the terminal voltage, usually  $I_d \leq 0$ .


field-weakening: at high speeds, make  $I_d$  smaller and smaller (more negative) to keep the terminal voltage to allowable limits

2. MAGNETIC FIELD EXPLANATION

the three phase coils in the machine are located 120° apart in space  
magnetic fields produced by a positive current in each phase, have axes which are 120° apart



12R006 DQ TRANSFORM AND IMPLEMENTATION

30-JAN-12



three phase balanced currents in three windings create a rotating magnetic field at synchronous speed whose magnitude is 1.5 times that produced by the peak field produced by each phase alone

rotating field equivalent to that produced by a rotating coil with a current of 1.5pu DC





can consider as a rotating current (phasor)

the rotor of a synchronous machine is also rotating at synchronous speed

consider a PM rotor, define d-axis as direction of PM flux and q-axis as 90° leading this


$t = t_1$

$i_a = 1$   
 $i_b = -0.5$   
 $i_c = -0.5$




$t = t_2$

$i_a = 0.866$   
 $i_b = 0$   
 $i_c = -0.866$



stator current phasor is not rotating relative to the rotor


synchronous reference frame




- magnet flux lies in positive d-axis, induced voltage is the rate of change of flux, thus leads magnet flux by 90°, hence in positive q-axis
- using negative values of Id reduces the flux in the d-axis and so reduces the q-axis voltage and hence terminal voltage (i.e. flux produced by stator current opposes magnet flux)
- torque produced by the rotor magnetic field wanting to align with the stator magnetic field.

basically a projection of the 3ph quantities onto 2 stationary axes, the 2/3 Factor ensures the peak value of  $\alpha, \beta$  the same as the peak value of  $a, b, c$  (remember the 1.5 factor in the previous section)

3) TRANSFORM IMPLEMENTATION




3.2. PARK TRANSFORM



$$\begin{bmatrix} i_d \\ i_q \end{bmatrix} = \begin{bmatrix} \cos \theta & \sin \theta \\ -\sin \theta & \cos \theta \end{bmatrix} \begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix}$$



rotating frame                      stationary frame

3.1. CLARKE TRANSFORM



$$\begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix} = \frac{2}{3} \begin{bmatrix} 1 & -0.5 & -0.5 \\ 0 & \sqrt{3}/2 & -\sqrt{3}/2 \end{bmatrix} \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix}$$

3.3. BLOCK DIAGRAM



$I = 1 \text{ pu}$        $I = 1 \text{ pu}$        $I_d^2 + I_q^2 = 1$

three-phase stationary frame      two-phase rotating frame (constant quantities in steady-state)

"Do not conform to the pattern of this world, but be transformed by the renewing of your mind."